

Content	Page
H 1	DRAWINGS3
H 1.1	Drawings of compressor, process piping and plant parts3
H 1.2	Drawings of instrumentation and control.....5
H 2	WORKS STANDARDS7
H 3	RECORDS, FORMS AND CHECK LISTS.....43
H 3.1	Coupling alignment record.....43
H 3.2	Setting of axial clearance.....44
H 3.3	Alignment record (template)45
H 3.4	Checklist for installation47
H 3.5	Checklist for commissioning49
H 4	INFORMATION ON SPARE PARTS AND NOTES ON INQUIRIES51
H 4.1	Structure of our centrifugal compressor plants51
H 4.2	Structure of our spare parts list.....53
H 4.3	Notes on how to order spares, example53
H 4.4	Spare parts delivered with the machine.....54
H 4.5	Spare parts list.....55
H 5	TECHNICAL DOCUMENTATION AND INSTRUCTION MANUALS OF AC'S SUB-SUPPLIERS.....59