

LIST OF SUBMITTED DOCUMENTATION


Project: 148 - ASU No. 9, U. S. Steel

Building: SO 006 – LAR Tank Foundation

- 1) Inspection Report – grounding
- 2) Certificate of Conformity Verification No. A 1.9/01/0004/1/C/C04 – highly-solid grouting mixtures PANBEX G1, G2, G3, G4, G5, G6, G7
- 3) Certificate of Conformity Verification No. A 1.5/01/1414/1/C/C04
- 4) Manufacturer's Declaration of Conformity Verification - bent reinforcement
- 5) Certificate of Quality and Completeness - bent reinforcement
- 6) SK - Declaration of Conformity No. 35/2005 – Concrete STN EN 206-1-C20/25-XC1(SK)
- 7) Confirmation of excavated soil storage
- 8) Statutory declaration on placement of the excavated soil in the embankments
- 9) As-built surveying
- 10) Test of Conformity – concrete STN EN 206-1-C20/25 XC1(SK)
- 11) Declaration of Conformity No. 0004_4_0503 – aggregate UHKT VP 0/70
- 12) Certificate of Conformity Verification No. 56055/03/0033/1/C/C04 – crystalline sealing mortar AQUAFIN

Košice,

Submitted by:

.....


Received by:

.....

COMMENT AL: 30/08/2006 *Rep*

- authorization for transport of the waste material is missing
- waste disposal for 567,03t is missing